PORSCHE 911 COUPE

Full Pre-Purchase Inspection Report



VIN	**WP0ZZZ99ZHS110834**
First Reg.	**—**
Mileage	**45 949 km**
Engine/Fuel	**3.0**
Transmission	**automatic · dual-clutch (PDK)**

Location	**Maastricht, NL**
Inspector	**DAExport**
Keys	**2**
Seller	**—**
Package	**Full inspection**

INSPECTOR SUMMARY

Cold start without hesitation, the engine runs evenly and the gearbox shifts smoothly. To repair before purchase: front left brake at the wear limit — 35% left, front right brake at the wear limit — 35% left, rear left brake at the wear limit — 30% left, rear right brake at the wear limit — 30% left. Coating thickness is even across all measured panels — no signs of bodywork repair. The bumpers were not measured — a magnetic/eddy-current gauge does not read plastic. We recommend this car at the asking price.

OVERALL RATING
9.5 / 10

RECOMMENDED

ENGINE & DRIVETRAIN

Cold Start	OK
Idle Stability	OK
Fluid Leaks (Top)	NONE
Fluid Leaks (Bottom)	NONE
Exhaust Smoke	CLEAN
Turbo Noise	OK
Coolant System	OK
Oil Condition	OK
Battery Health	OK
Transmission Shift	SMOOTH

INTERIOR & ELECTRONICS

Dashboard	CLEAN
Seats & Upholstery	OK
Steering Wheel	OK
AC / Climate	COLD
Windows/Mirrors	OK
Infotainment	OK
Seat Heating	OK
Seat Belts	OK
Interior Odor	FRESH
Lighting System	OK

SUSPENSION & BRAKES

Test Drive	OK
Steering Play	NONE
Suspension Noise	NONE
Brake Feel	OK
Handbrake	OK
Shock Absorbers	OK
Undercarriage Rust	OK
Tires (Front)	OK
Tires (Rear)	OK

DOCUMENTS

Registration Part 1	N/A
Registration Part 2	N/A
COC Certificate	YES
Service History	YES
Inspection Valid	VALID
Manuals	YES
Spare Keys	YES

WHEEL STATUS (MM)

FRONT LEFT	FRONT RIGHT
5.34 mm	5.39 mm
OK	OK

REAR LEFT	REAR RIGHT
3.74 mm	3.61 mm
OK	OK

BRAKES HEALTH (%)

FRONT LEFT	FRONT RIGHT
35%	35%
Need to be changed	Need to be changed

REAR LEFT	REAR RIGHT
30%	30%
Need to be changed	Need to be changed

PAINT THICKNESS (µm)

PANEL	THICKNESS (µm)	STATUS	NOTE
Front Bumper	—	—	plastic — not measured
Hood	**120**	OK	—
Front Left Fender	**110**	OK	—
Front Left Door	**112**	OK	—
Rear Left Door	**126**	OK	—
Left Rear Corner	**128**	OK	—
Front Right Fender	**121**	OK	—
Front Right Door	**100**	OK	—
Rear Right Door	**120**	OK	—
Right Rear Corner	**130**	OK	—
Trunk	**100**	OK	—

CONDITION SUMMARY

4 defect(s) · 0 to watch · 48 without remarks

NEEDS ATTENTION


DEFECTS

Brake · Front Left	35 %
Brake · Front Right	35 %
Brake · Rear Left	30 %
Brake · Rear Right	30 %

IN GOOD ORDER

- **Engine**
  checked items: 8 — no remarks
- **Gearbox & drivetrain**
  checked items: 2 — no remarks
- **Front axle: brakes, suspension, steering**
  7 of 9 without remarks
- **Rear axle: brakes, tyres**
  4 of 6 without remarks
- **Underbody & corrosion**
  checked items: 1 — no remarks
- **Interior & electronics**
  checked items: 9 — no remarks
- **Electrics & lighting**
  checked items: 2 — no remarks
- **Body panels (paint)**
  checked items: 10 — no remarks

Without remarks: 48 of 52 checked items



4 finding(s)

Engine	OK
Gearbox & drivetrain	OK
Front axle: brakes, suspension, steering	DEFECT
Rear axle: brakes, tyres	DEFECT
Underbody & corrosion	OK
Interior & electronics	OK
Electrics & lighting	OK
Body panels (paint)	OK

ESTIMATED REPAIR COST

Indicative estimate prepared automatically from the findings above, at typical independent workshop rates in Belgium and the Netherlands. It is not a workshop quote and does not bind any garage. Use it as an argument in the price negotiation.

FINDING	RECOMMENDED WORK	COST
● **Brake · Front Left + Right**	Brake pads and discs replacement (per axle)	**350–800 €**
● **Brake · Rear Left + Right**	Brake pads and discs replacement (per axle)	**350–800 €**
Estimated total		**700–1 600 €**

DIGITAL ATTACHMENTS

The complete photo & video documentation, the full OBD diagnostic scan and the vehicle history report are hosted online. Open this report in any PDF reader and tap a button below to access them.

Photos & Videos
Open gallery ↗

Full OBD Scan
TOPDON report ↗

Vehicle history report
Full vehicle history by VIN ↗